



Exhibit 4

BADGER ELEMENTARY SCHOOL - BIKE AND WALK AUDIT RESULTS

- BIKE RACKS
-  CROSSING GUARD
-  PEOPLE DRIVING TOO FAST
-  FOOTPATH
-  NO SIDEWALK
-  PAINTED CROSSWALK
-  PARENT PICK-UP AND DROP-OFF
-  BADGER ELEMENTARY SCHOOL
-  BUS LOADING AND UNLOADING
-  FACULTY AND STAFF PARKING

DRAFT

Source: Outagamie County provided 2008 centerline, municipality boundaries, and hydrology data. ECWRPC provided school location data. ECWRPC and the Grand Chute SRTS Task Force provided bike and walk audit results.



Scale in Feet

This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Prepared By
EAST CENTRAL WISCONSIN
REGIONAL PLANNING COMMISSION-DECEMBER 2008

