



# Exhibit 14

## WEBSTER STANLEY ELEMENTARY & MIDDLE SCHOOLS - BIKE AND WALK AUDIT RESULTS

-  Webster Stanely Elementary and Middle Schools
-  Bus Stop
-  Dangerous Dumpster
-  Dog
-  Student Crossing Guard
-  Bad Sidewalk
-  Bad dog area
-  Bus Loading Zone
-  Congestion Area
-  Crosswalk
-  Excessive Speed
-  No Parking
-  One-Way
-  Overgrown Hedge
-  Sidewalk rough
-  Yellow curb

Source: Winnebago County provided 2007 centerline, municipality boundaries, school district, hydrology data, and 2005 aerial photography. ECWRPC provided bike and walk audit results.



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Prepared By  
EAST CENTRAL WISCONSIN  
REGIONAL PLANNING COMMISSION-NOVEMBER 2008

